DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/06/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY COMPLETED	
			A. BUILDING 01,02		IG 01,02	_	
		155121	B. WING			R 08/02/2012	
NAME OF PROVIDER OR SUPPLIER ROSEWALK VILLAGE AT LAFAYETTE					REET ADDRESS, CITY, STATE, ZIP CODE 1903 UNION ST LAFAYETTE, IN 47904		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREF TAG		PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUI CROSS-REFERENCED TO THE APPRO DEFICIENCY)	OULD BE COMPLETION	
{K 000}			(K (000	}		
	Code Recertification a conducted 06/05/12 a Walk-thru Survey wer	it (PSR) to the Life Safety and State Licensure Survey and Quality Assurance re conducted by the Indiana Health in accordance with 42					
	Survey Date: 08/02/1	2					
	Facility Number: 0000 Provider Number: 159 AIM Number: 100275	5121					
	Surveyor: Bridget Bro Specialist	own, Life Safety Code					
	survey, Rosewalk Vill compliance with Requ Medicare/Medicaid, 4 Life Safety from Fire a National Fire Protecti Life Safety Code (LSG	lity Assurance Walk-thru lage was found in uirements for Participation in 12 CFR Subpart 483.70(a), and the 2000 edition of the on Association (NFPA) 101, C), Chapter 19, Existing incies and 410 IAC 16.2.					
	building with a one st a one story Physical first floor D wing, and construction was dete (211) and completed facility has a fire alarr smoke detection in th open to the corridors detectors protect eac	isted of the original two story ory section on the front, and Therapy wing added to the was fully sprinklered. The ermined to be of Type III prior to March 1, 2003. The m system with hard wired e corridors and spaces Battery powered smoke h resident room. The facility 55 residents and had a					
LABORATORY		SUPPLIER REPRESENTATIVE'S SIGNATURE			TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/06/2012 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER ROSEWALK VILLAGE AT LAFAYETTE STREET ADDRESS, CITY, STATE, ZIP CODE 1903 UNION ST LAFAYETTE, IN 47904 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION (X5)	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		DENTIFICATION NUMBER:			PLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER ROSEWALK VILLAGE AT LAFAYETTE STREET ADDRESS, CITY, STATE, ZIP CODE 1903 UNION ST LAFAYETTE. IN 47904						9 01,02	R	
ROSEWALK VILLAGE AT LAFAYETTE (X4) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) [K 000] Continued From page 1 The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage. All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered. Quality Review by Lex Brashear, Life Safety Code	155121		155121	B. WING				
PRÉFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (K 000) (K 000) (K 000) (K 000) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (K 000) (K 000) (K 000) (K 000) (K 000) (K 000) (All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered. (Quality Review by Lex Brashear, Life Safety Code)					19	903 UNION ST		
The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage. All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered. Quality Review by Lex Brashear, Life Safety Code	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX		(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO	SHOULD BE COMPLETION	
	{K 000}	The facility was found law in regard to sprint detector coverage. All areas where the reaccess were sprinkled facility services were Quality Review by Let	d in compliance with state kler coverage and smoke esidents have customary red and all areas providing sprinklered. x Brashear, Life Safety Code	{K (000}	·		